

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	310660
License plate	EB7705
Vehicle identification number	VSSZZZKJXRR064920
Dossier	2023215028
Make	Seat Ibiza 1.0eTSi 110 Xcellen
Mileage	59789
First registration	05/02/2024
client availability date	15/04/2026
inspectionDate	17/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
81	Door Front Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
196	Door Rear Right // Polish	Y
331	Wheel Alloy Rear Right // Repair	Y
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Seat Rear Left // Repair-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Bumper Front // Painting-scratch



Door Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch



Interior Cleaning // Small-stain