

INSPECTION REPORT


End of contract

GENERAL INFO

File	321662
License plate	2APW664
Vehicle identification number	W0V7D9EN9M4180613
Dossier	2021083014
Make	Opel Crossland 1.5D 81kW Editi
Mileage	89353
First registration	07/06/2021
client availability date	08/09/2026
inspectionDate	17/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		N	
Repair kit		N	
RunOnFlat		Y	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
165	Roof // Polish	Y
196	Door Rear Right // Polish	Y
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
860	Interior Cleaning // Small	Y

Damage Pictures



Wheel Rear Left / Wheel Cover / Replace-scratch



Front Bonnet // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Wheel Front Left / Wheel Cover / Replace-scratch




Wheel Rear Right / Wheel Cover / Replace-scratch



Door Rear Right // Polish-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Roof // Polish-Chemical reaction



Interior Cleaning // Small-dirty