

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309198
License plate	2ADJ587
Vehicle identification number	W1K1770121N223623
Dossier	2020296081
Make	Mercedes A 200 d Busin.Sol.Lim
Mileage	103423
First registration	26/02/2021
client availability date	26/03/2026
inspectionDate	31/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
223	Side View Mirror Right // Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
15	Bumper Front // Replace & Painting	N
18	Bumper Front / Spoiler / Replace	N
274	Bumper Front / Grid Central / Replace	N
84	Door Front Left // Repair & Painting	N
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
31	Front Bonnet // Smart Repair Small	N
41	Windshield // Replace	Y
60	Wing Front Left // Smart Repair Small	N
72	Side View Mirror Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
92	Rocker Panel Left // Painting	N
124	Light / Rear left / Replace	Y
134	Bumper Rear // Repair & Painting	N
153	Rear Bonnet // Painting	Y
157	Rear Bonnet / Trim / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
168	Roof / Medium Panoramic Roof / Replace	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
186	Wing Rear Right // Polish	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
233	Wing Front right // Painting	Y

311	Wheel Alloy Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
773	Interior / A Pillar Lower Cover / Replace	Y
860	Interior Cleaning // Small	N


### Damage Pictures




Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Light / Rear Right / Replace-scratch



Rocker Panel Left // Painting-scratch



Side View Mirror Left // Painting-scratch




Wheel Alloy Front Left // Repair-scratch



Windshield // Replace-scratch



Light / Rear left / Replace-scratch




Roof / Medium Panoramic Roof / Replace-scratch



Seat Front Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wing Front Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Front Bonnet // Smart Repair Small-dent




Door Front Right // Smart Repair Small-scratch



Rear Bonnet / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Bumper Rear // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Front right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Interior Cleaning // Small-dirty



Interior / A Pillar Lower Cover / Replace-bad position






Side View Mirror Right // Replace Not Painted-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Bumper Front / Spoiler / Replace-cracked



Bumper Front // Replace & Painting-cracked




Bumper Front / Grid Central / Replace-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent