

INSPECTION REPORT

End of contract


GENERAL INFO

File	321004
License plate	SM2402
Vehicle identification number	W1N2476121W242812
Dossier	2022056030
Make	Mercedes GLB 200d 150 Luxury L
Mileage	58667
First registration	29/08/2022
client availability date	27/08/2026
inspectionDate	01/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Spoiler / Replace-scratch + dent