

INSPECTION REPORT


End of contract

GENERAL INFO

File	313676
License plate	2EHD488
Vehicle identification number	YV1ZWK7V9P2538949
Dossier	2023 158 227
Make	Volvo V60 B3 Core DCT
Mileage	23993
First registration	10/10/2023
client availability date	01/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
86	Door Front Left // Polish	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
169	Rear Bonnet / Spoiler / Replace & Painting	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
214	Door Front Right // Repair & Painting	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y

Damage Pictures



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Polish-scratch




Wheel Two Tone Rear Left // Repair-scratch



Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Polish-Chemical reaction



Front Bonnet // Polish-Chemical reaction



Roof // Polish-Chemical reaction




Rear Bonnet // Polish-Chemical reaction





Bumper Rear // Polish-Chemical reaction



Rear Bonnet / Spoiler / Replace & Painting-Chemical reaction



Wing Rear Right // Polish-Chemical reaction



Door Rear Right // Polish-Chemical reaction



Wing Rear Left // Polish-Chemical reaction



Door Front Left // Polish-Chemical reaction



Door Rear Left // Polish-Chemical reaction