

INSPECTION REPORT



End of contract

GENERAL INFO

File	316192
License plate	1YAF641
Vehicle identification number	W1K1770021N174521
Dossier	2020021072
Make	Mercedes A 160 d Business Solu
Mileage	118203
First registration	29/06/2020
client availability date	29/06/2026
inspectionDate	29/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
38	Front Bonnet / Insulation / Replace	N
60	Wing Front Left // Smart Repair Small	Y
134	Bumper Rear // Repair & Painting	Y
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	N
213	Door Front Right // Painting	Y
282	Bumper Rear / Trim Center / Replace	N
320	Wheel Two Tone Rear Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y

Damage Pictures



Roof // Polish-scratch




Bumper Front // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Rear Right // Painting-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch




Wing Front Left // Smart Repair Small-dent



Bumper Rear / Trim Center / Replace-cracked



Door Rear Right / Trim / Replace-cracked



Seat Front Left / Rear Coating / Replace-worn



Bumper Rear // Repair & Painting-Chipped paint



Front Bonnet / Insulation / Replace-hole