

INSPECTION REPORT



End of contract

GENERAL INFO

File	322432
License plate	2BHK698
Vehicle identification number	SB1Z93BE10E268232
Dossier	2021274021
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	149849
First registration	26/11/2021
client availability date	16/09/2026
inspectionDate	23/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
13	Bumper Front // Painting	N
80	Door Front Left // Smart Repair Small	N
104	Door Rear Left // Repair & Painting	N
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
233	Wing Front right // Painting	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Bumper Rear // Painting-scratch




Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Repair & Painting-scratch + dent



Tyre Front Right // Replace-tear




Interior Cleaning // Small-stain



Bumper Front // Painting-Chipped paint



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch