

INSPECTION REPORT


End of contract

GENERAL INFO

File	313571
License plate	MF7821
Vehicle identification number	W1N2477121J385032
Dossier	2021089084
Make	Mercedes GLA 200d 150 Bus Sol
Mileage	115392
First registration	06/04/2022
client availability date	22/05/2026
inspectionDate	27/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures



Wheel Two Tone Rear Left // Repair-Chemical reaction



Seat Front Left / Rear Coating / Replace-tear



Dashboard / Steering Wheel / Replace-worn



Bumper Rear // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Smart Repair Small-dent



Door Rear Right // Repair & Painting-dent



Door Front Right // Repair & Painting-scratch + dent