

INSPECTION REPORT




End of contract

GENERAL INFO

File	314138
License plate	2BSR532
Vehicle identification number	W1N2533161G037632
Dossier	2021256064
Make	Mercedes GLC Coupé 200d 4M Bus
Mileage	39648
First registration	09/03/2022
client availability date	04/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
161	Roof // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
412	Seat Front Left / Bottom Coating / Replace	Y

Damage Pictures



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Roof // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Seat Front Left / Bottom Coating / Replace-worn