

INSPECTION REPORT

End of contract

GENERAL INFO

File	308011
License plate	2ADK630
Vehicle identification number	W1N2477101J224270
Dossier	2020190106
Make	Mercedes GLA 180 d Bus.Solutio
Mileage	89760
First registration	01/03/2021
client availability date	20/03/2026
inspectionDate	30/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
80	Door Front Left // Smart Repair Small	Y
95	Rocker Panel Left // Polish	Y

Damage Pictures



Damage within Renta-norm-



Door Front Left // Smart Repair Small-scratch



Rocker Panel Left // Polish-scratch



Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch