

INSPECTION REPORT


End of contract

GENERAL INFO

File	307827
License plate	2BUJ569
Vehicle identification number	W1N2477861J385302
Dossier	2021278063
Make	Mercedes GLA 250e Business Sol
Mileage	53657
First registration	25/03/2022
client availability date	03/04/2026
inspectionDate	07/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
67	Wing Front Left / Trim / Replace	N
273	Bumper Front / Grid Left / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
150	Rear Bonnet // Smart Repair Small	N
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	Y
271	Bumper Front / Trim Left / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures







Damage within Renta-norm-



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Front Right // Repair-Chemical reaction



Wheel Two Tone Front Left // Repair-Chemical reaction



Light / Rear Right / Replace-N comf / out of order



Bumper Front / Trim Left / Replace-scratch



Light / Rear left / Replace-scratch



Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Grid Left / Replace-scratch