

# INSPECTION REPORT



**End Of Contract**

## GENERAL INFO

File	283839
License plate	2BHY858
Vehicle identification number	WVGZZZC1ZNY032447
Dossier	2021326055
Make	Volkswagen T-Cross 1.0TSI 70kW
Mileage	32588.00
First registration	02/12/2021
	04/06/2025

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
12	Bumper Front // Smart Repair Large	N
18	Bumper Front / Spoiler / Replace	N
110	Wing Rear Left // Smart Repair Small	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
213	Door Front Right // Painting	N
315	Wheel Front Left / Hub Cover With Logo / Replace	N
325	Wheel Rear Left / Hub Cover With Logo // Replace	N
335	Wheel Rear Right / Hub Cover with Logo / Replace	N
345	Wheel Front Right / Hub Cover with Logo / Replacement	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

## Damage Pictures





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet / Rear Window / Replace-scratch






Bumper Rear // Painting-scratch




Bumper Front // Smart Repair Large-scratch



Wing Rear Left // Smart Repair Small-dent



Bumper Front / Spoiler / Replace-dent



Door Front Right // Painting-scratch + dent



Wheel Rear Right / Hub Cover with Logo / Replace-missing



Wheel Rear Left / Hub Cover With Logo // Replace-missing



Wheel Front Left / Hub Cover With Logo / Replace-missing



Wheel Front Right / Hub Cover with Logo / Replacement-missing



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch