

INSPECTION REPORT

End of contract

GENERAL INFO

File	319481
License plate	2ERR084
Vehicle identification number	W1K1K1EB4PF210533
Dossier	2023363012
Make	Mercedes E220D Cabrio 143kW Au
Mileage	52180
First registration	05/01/2024
client availability date	11/08/2026
inspectionDate	01/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
136	Bumper Rear // Polish	Y
210	Door Front Right // Smart Repair Small	Y
318	Flat Tyre Kit // Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures





Bumper Rear // Polish-scratch




Wheel Two Tone Rear Right // Repair-scratch




Door Front Right // Smart Repair Small-scratch





Wheel Two Tone Front Right // Repair-scratch



Door Front Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-dirty



Tyre Rear Right // Replace-tear



Seat Front Left / Bottom Coating / Replace-worn