

INSPECTION REPORT


End of contract


GENERAL INFO

File	321371
License plate	1XAA319
Vehicle identification number	WDD1771031J156878
Dossier	2019 169 047
Make	Mercedes A Berline 180 d Bus.S
Mileage	71430
First registration	22/10/2019
client availability date	07/09/2026
inspectionDate	15/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
213	Door Front Right // Painting	N
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
801	See External Expertise	N
12	Bumper Front // Smart Repair Large	N
38	Front Bonnet / Insulation / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
112	Wing Rear Left // Smart Repair Large	N
134	Bumper Rear // Repair & Painting	N
153	Rear Bonnet // Painting	Y
162	Roof // Painting	N
181	Wing Rear Right // Smart Repair Medium	N
222	Side View Mirror Right // Painting	Y
235	Wing Front right // Replace & Painting	N
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
554	Central Console // Replace Completely	Y
569	Dashboard / Steering Wheel / Replace	Y
890	Remove mold	N

Damage Pictures



Central Console // Replace Completely-N comf / out of order



Bumper Front // Smart Repair Large-scratch



Side View Mirror Right // Painting-scratch



Wing Rear Right // Smart Repair Medium-dent



Remove mold-



Wheel Two Tone Front Right // Repair-scratch



Rear Bonnet // Painting-scratch



Wing Front right // Replace & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Left // Smart Repair Large-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Roof // Painting-Chemical reaction



Wheel Two Tone Rear Left // Repair-Chemical reaction



Front Bonnet / Insulation / Replace-tear





Dashboard / Steering Wheel / Replace-worn




Door Front Right // Painting-scratch



Door Rear Right // Repair & Painting-scratch + dent



See External Expertise-stone chipping



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch