

INSPECTION REPORT

End of contract

GENERAL INFO

File	306630
License plate	1YDR239
Vehicle identification number	VF3MCYHZRLS174700
Dossier	2020 041 005
Make	Peugeot 3008 1.5BHdi 96kW Acti
Mileage	71770
First registration	29/07/2020
client availability date	11/03/2026
inspectionDate	14/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
201	Rocker Panel Right // Smart Repair Medium	N

Damage Pictures



Damage within Renta-norm-



Rocker Panel Right // Smart Repair Medium-scratch + dent