

INSPECTION REPORT

End of contract

GENERAL INFO

File	309190
License plate	2DGE897
Vehicle identification number	SJNTBAJ12U1229187
Dossier	2022 286 032
Make	Nissan Qashqai 1.5eP190 N-Conn
Mileage	126992
First registration	09/03/2023
client availability date	30/03/2026
inspectionDate	09/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
540	Interior // Repair 1	N
565	Dashboard / Storage Tray / Replace	N
116	Wing Rear Left // Polish	N
124	Light / Rear left / Replace	N
13	Bumper Front // Painting	Y
41	Windshield // Replace	N
72	Side View Mirror Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	N
133	Bumper Rear // Painting	N
174	Light / Rear Right / Replace	N
210	Door Front Right // Smart Repair Small	Y
226	Side View Mirror Right / Shell / Replace Painted	N
271	Bumper Front / Trim Left / Replace	Y
282	Bumper Rear / Trim Center / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
634	Rear Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N
883	Key Price Range 2 //	Y

Damage Pictures



Rear Right Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Replace-cracked



Side View Mirror Right / Shell / Replace Painted-cracked



Interior Cleaning // Small-stain



Key Price Range 2 //-worn



Bumper Front // Painting-stone chipping



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch






Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Trim Left / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Painting-scratch



Interior // Repair 1-scratch



Dashboard / Storage Tray / Replace-scratch



Light / Rear left / Replace-scratch



Wing Rear Left // Polish-scratch