

INSPECTION REPORT


End of contract

GENERAL INFO

File	318396
License plate	2CFF120
Vehicle identification number	VF3MCYHZUNS055522
Dossier	2022025094
Make	Peugeot 5008 1.5BHdi 96kW GT A
Mileage	144403
First registration	30/06/2022
client availability date	23/07/2026
inspectionDate	10/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
46	Windshield / Rear View Mirror / Replace	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
84	Door Front Left // Repair & Painting	N
89	Door Front Left / Window / Replace	Y
134	Bumper Rear // Repair & Painting	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
538	Trunk Compartment / Boot Cover / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-dent



Door Front Right // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent



Trunk Compartment / Boot Cover / Replace-missing





Interior Cleaning // Small-dirty



Bumper Rear // Repair & Painting-bad position



Door Front Left / Window / Replace-scratch



Windshield / Rear View Mirror / Replace-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Wheel Two Tone Front Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch







Rear Bonnet // Polish-scratch






Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Left // Repair & Painting-dent




Door Rear Right // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-cracked



Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Smart Repair Medium-dent