

INSPECTION REPORT

End of contract


GENERAL INFO

File	319557
License plate	2ATW042
Vehicle identification number	W1K1771121J323782
Dossier	2020 329 036
Make	Mercedes A Berline 200 d Aut.
Mileage	146704
First registration	14/07/2021
client availability date	04/08/2026
inspectionDate	20/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
203	Rocker Panel Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	N
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	N
221	Side View Mirror Right // Plastic Repair	N
228	Side View Mirror Right / Direction Indicator / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wing Rear Left // Repair & Painting-bad repair



Front Bonnet // Polish-Chemical reaction



Wheel Two Tone Rear Left // Repair-Chemical reaction



Interior Cleaning // Small-dirty



Dashboard / Steering Wheel / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch




Wing Rear Right // Painting-scratch



Door Rear Right // Painting-scratch



Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch




Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent