

# INSPECTION REPORT




**End of contract**


## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 311922                         |
| License plate                 | 2BWA809                        |
| Vehicle identification number | VF3M4DGZUNS059656              |
| Dossier                       | 2021 347 133                   |
| Make                          | Peugeot 3008 PHEV 165kW Roadtr |
| Mileage                       | 72282                          |
| First registration            | 13/04/2022                     |
| client availability date      | 05/06/2026                     |
| inspectionDate                | 12/06/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                                  | Acceptable |
|---------|-------------------------------------------------------|------------|
| 117     | Wing Rear Left / Trim / Replace                       | N          |
| 161     | Roof // Smart Repair Medium                           | N          |
| 81      | Door Front Left // Smart Repair Medium                | Y          |
| 101     | Door Rear Left // Smart Repair Medium                 | Y          |
| 131     | Bumper Rear // Smart Repair Medium                    | Y          |
| 175     | Light / Rear Right On Rear Bonnet / Replace           | Y          |
| 180     | Wing Rear Right // Smart Repair Small                 | Y          |
| 190     | Door Rear Right // Smart Repair Small                 | Y          |
| 310     | Wheel Two Tone Front Left // Repair                   | Y          |
| 412     | Seat Front Left / Bottom Coating / Replace            | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace | Y          |
| 634     | Rear Left Door Interior Coating // Replace Completely | N          |
| 774     | Interior / Side Cover rear Seat / Replace             | Y          |

## Damage Pictures



Door Rear Right // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-scratch + dent



Seat Front Left / Bottom Coating / Replace-worn



Light / Rear Right On Rear Bonnet / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Two Tone Front Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch






Door Rear Left // Smart Repair Medium-scratch



Bumper Rear // Smart Repair Medium-scratch



Wing Rear Left / Trim / Replace-



Roof // Smart Repair Medium-dent