

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307801
License plate	1YFW753
Vehicle identification number	YV1ZW72V1M2416058
Dossier	2020141034
Make	Volvo V60 D3 Momentum Pro
Mileage	125916
First registration	18/08/2020
client availability date	11/03/2026
inspectionDate	23/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
140	Back Side // Smart Repair Medium	N
146	Back Side / Reflector L / Replace	N
13	Bumper Front // Painting	N
274	Bumper Front / Grid Central / Replace	N
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
540	Interior // Repair 1	N

## Damage Pictures



Damage within Renta-norm-scratch



Interior // Repair 1-Incinerated



Windshield // Repair-glass damage



Wing Front Left // Painting-stone chipping



Back Side // Smart Repair Medium-scratch



Back Side / Reflector L / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Front / Grid Central / Replace-scratch



Bumper Front // Painting-scratch