

INSPECTION REPORT


End of contract

GENERAL INFO

File	311533
License plate	2BGZ495
Vehicle identification number	TMBJN7NP2N7012864
Dossier	2021053044
Make	Skoda Sup.Comb.TSI 150 Clever
Mileage	68345
First registration	23/11/2021
client availability date	24/04/2026
inspectionDate	30/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
183	Wing Rear Right // Painting	N
194	Door Rear Right // Repair & Painting	N
81	Door Front Left // Smart Repair Medium	N
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
222	Side View Mirror Right // Painting	Y
331	Wheel Alloy Rear Right // Repair	N

Damage Pictures



Wing Rear Left // Repair & Painting-scratch + dent



Door Front Left // Smart Repair Medium-bad position



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch




Side View Mirror Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Door Rear Right // Repair & Painting-scratch + dent