

INSPECTION REPORT




End Of Contract

GENERAL INFO

File	282823
License plate	2ARV668
Vehicle identification number	WAUZZZGY1MA132078
Dossier	2021 127 070
Make	Audi A3 Ber.30 TFSi 81kW S li.
Mileage	59006.00
First registration	25/06/2021
	30/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
133	Bumper Rear // Painting	N
184	Wing Rear Right // Repair & Painting	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch




Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Bumper Front / Trim Right / Replace-Chipped paint