

INSPECTION REPORT


End of contract

GENERAL INFO

File	309020
License plate	2FJG073
Vehicle identification number	SJNFAAF16U1286833
Dossier	2023361018
Make	Nissan Juke 1.0 84kW N-Design
Mileage	29139
First registration	21/05/2024
client availability date	25/03/2026
inspectionDate	27/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
18	Bumper Front / Spoiler / Replace	Y
109	Door Rear Left / Window / Replace	N
210	Door Front Right // Smart Repair Small	N
222	Side View Mirror Right // Painting	Y
237	Wing Front right / Trim / Replace	N

Damage Pictures




Side View Mirror Right // Painting-scratch



Wing Front right / Trim / Replace-scratch



Door Rear Left / Window / Replace-scratch



Door Front Right // Smart Repair Small-dent



Bumper Front / Spoiler / Replace-Chipped paint



Front Bonnet / Insulation / Replace-hole