

INSPECTION REPORT


End of contract


GENERAL INFO

File	312856
License plate	2DHC462
Vehicle identification number	VF3MCYHZUPS032811
Dossier	2022 364 058
Make	Peugeot 3008 1.5BHDi 96kW Acti
Mileage	50457
First registration	17/03/2023
client availability date	13/05/2026
inspectionDate	19/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
12	Bumper Front // Smart Repair Large	Y
40	Windshield // Repair	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
228	Side View Mirror Right / Direction Indicator / Replace	N
283	Bumper Rear / Trim Right / Replace	Y
311	Wheel Alloy Front Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Windshield // Repair-glass damage



Interior Cleaning // Small-stain




Side View Mirror Right / Direction Indicator / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Door Rear Right / Trim / Replace-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Bumper Rear / Trim Right / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent