

INSPECTION REPORT



End of contract

GENERAL INFO

File	316194
License plate	2CFP837
Vehicle identification number	TMBJJ7NSXN8038073
Dossier	2022165058
Make	Skoda Kod.2.0CRTDI 110kW Cle+D
Mileage	205214
First registration	05/07/2022
client availability date	12/07/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	Y
153	Rear Bonnet // Painting	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
237	Wing Front right / Trim / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	Y

Damage Pictures




Door Rear Left // Painting-scratch



Rear Left Door Interior Coating // Repair-scratch




Door Rear Right // Polish-scratch



Door Front Right // Painting-scratch



Wing Front right / Trim / Replace-scratch



Rear Bonnet // Painting-scratch



Interior Cleaning // Small-stain