

INSPECTION REPORT



End of contract

GENERAL INFO

File	309181
License plate	2ACQ179
Vehicle identification number	VSSZZZ5FZM6544915
Dossier	2020 317 074
Make	Seat Ateca 2.0TDI 150 Move DSG
Mileage	160311
First registration	19/02/2021
client availability date	31/03/2026
inspectionDate	03/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	Y
81	Door Front Left // Smart Repair Medium	Y
153	Rear Bonnet // Painting	Y
165	Roof // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Roof // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Front / Spoiler / Replace-dent





Bumper Front // Painting-bad repair



Rear Bonnet // Painting-bad repair



Wheel Two Tone Front Left // Repair-Chemical reaction



Interior Cleaning // Small-stain