

INSPECTION REPORT


End of contract

GENERAL INFO

File	310509
License plate	QR4360
Vehicle identification number	TMAJD81AGNJ268505
Dossier	2022055006
Make	Hyundai TUCSON 1.6CRDi 136 Fee
Mileage	171448
First registration	29/11/2022
client availability date	14/04/2026
inspectionDate	16/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
31	Front Bonnet // Smart Repair Small	N
103	Door Rear Left // Painting	Y
111	Wing Rear Left // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	Y
196	Door Rear Right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Smart Repair Medium-scratch



Door Rear Left // Painting-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Front Bonnet // Smart Repair Small-scratch + dent