

INSPECTION REPORT






End of contract

GENERAL INFO

File	320554
License plate	2AWM491
Vehicle identification number	TMBJP6NJ1NZ011404
Dossier	2021154043
Make	Skoda Fabia.Com.1.0TSI 70kW Am
Mileage	89979
First registration	17/08/2021
client availability date	26/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
452	Seat Rear Right / Bottom Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
540	Interior // Repair 1	N
540	Interior // Repair 1	N
857	Navigation Software // Replace	N
860	Interior Cleaning // Small	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch




Trunk Compartment / Side Cover Left / Replace-scratch



Side View Mirror Right // Painting-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Roof // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-dent




Door Front Right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Seat Rear Right / Bottom Coating / Replace-Incinerated



Navigation Software // Replace-missing



Bumper Front // Polish-Chemical reaction



Interior // Repair 1-tear



Interior // Repair 1-hole



Interior Cleaning // Small-stain