

# INSPECTION REPORT


**End of contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 321128                         |
| License plate                 | 2CMN067                        |
| Vehicle identification number | W1K5M8GB2PN343167              |
| Dossier                       | 2022034115                     |
| Make                          | Mercedes CLA SB 250 e Business |
| Mileage                       | 120290                         |
| First registration            | 16/09/2022                     |
| client availability date      | 02/09/2026                     |
| inspectionDate                | 08/09/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | Y       |        |
| Charge back wrong tyres   |        | Y       |        |





## DAMAGES

| Damages | Type                                                  | Acceptable |
|---------|-------------------------------------------------------|------------|
| 891     | Lettering Removal 15min                               | N          |
| 14      | Bumper Front // Repair & Painting                     | N          |
| 27      | Front / Logo / Replace                                | N          |
| 44      | Windshield / Trim / Replace                           | Y          |
| 81      | Door Front Left // Smart Repair Medium                | Y          |
| 91      | Rocker Panel Left // Smart Repair Medium              | Y          |
| 136     | Bumper Rear // Polish                                 | Y          |
| 147     | Back Side / Whiper Arm / Replace                      | N          |
| 152     | Rear Bonnet // Smart Repair Large                     | N          |
| 156     | Rear Bonnet // Polish                                 | Y          |
| 161     | Roof // Smart Repair Medium                           | Y          |
| 175     | Light / Rear Right On Rear Bonnet / Replace           | N          |
| 181     | Wing Rear Right // Smart Repair Medium                | Y          |
| 239     | Wing Front right / Inner Fender / Replace             | Y          |
| 311     | Wheel Alloy Front Left // Repair                      | Y          |
| 321     | Wheel Alloy Rear Left // Repair                       | Y          |
| 538     | Trunk Compartment / Boot Cover / Replace              | Y          |
| 569     | Dashboard / Steering Wheel / Replace                  | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace | Y          |
| 860     | Interior Cleaning // Small                            | N          |

## Damage Pictures



Wing Front right / Inner Fender / Replace-bad position



Rear Bonnet // Polish-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Front Left // Repair-scratch




Windshield / Trim / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Bumper Front // Repair & Painting-scratch + dent



Rear Bonnet // Smart Repair Large-scratch + dent



Front / Logo / Replace-cracked



Back Side / Whiper Arm / Replace-cracked




Light / Rear Right On Rear Bonnet / Replace-cracked



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Trunk Compartment / Boot Cover / Replace-worn



Wing Rear Right // Smart Repair Medium-stone chipping



Lettering Removal 15min-Remainder stickers