

INSPECTION REPORT

End of contract

GENERAL INFO

File	307654
License plate	2AGE539
Vehicle identification number	W1K1186101N211470
Dossier	2020 346 049
Make	Mercedes CLA SB 180 d Bus.Sol.
Mileage	90093
First registration	24/03/2021
client availability date	23/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13 Bumper Front // Painting		N

Damage Pictures



Damage within Renta-norm-



Bumper Front // Painting-scratch