

INSPECTION REPORT

End of contract


GENERAL INFO

File	318268
License plate	2BRC433
Vehicle identification number	YV1XZBWVFN2755366
Dossier	2021 258 063
Make	Volvo XC40 T4 PHEV R-Design.Gt
Mileage	152321
First registration	22/02/2022
client availability date	27/07/2026
inspectionDate	14/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
109	Door Rear Left / Window / Replace	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
161	Roof // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
237	Wing Front right / Trim / Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Interior Cleaning // Small-stain



Door Front Right // Polish-scratch



Wing Front right / Trim / Replace-scratch



Wing Front Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Roof // Smart Repair Medium-scratch



Door Rear Left / Window / Replace-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch





Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch