

INSPECTION REPORT


End of contract

GENERAL INFO

File	313173
License plate	1XCL265
Vehicle identification number	YV1UZADVDL1512160
Dossier	2019218050
Make	Volvo XC60 D4 163 Momentum Pro
Mileage	201587
First registration	15/11/2019
client availability date	19/05/2026
inspectionDate	28/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
146	Back Side / Reflector L / Replace	N
258	Towing Cover Rear // Replace	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
210	Door Front Right // Smart Repair Small	Y
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N
881	Key Price Range 1 //	N

Damage Pictures



Interior // Repair 1-cracked



Windshield // Repair-glass damage



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Towing Cover Rear // Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Back Side / Reflector L / Replace-cracked