

# INSPECTION REPORT

End of contract


## GENERAL INFO

File	313805
License plate	JV5889
Vehicle identification number	VR3USHNSSNJ662352
Dossier	2021342008
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	110696
First registration	26/07/2022
client availability date	27/05/2026
inspectionDate	01/06/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
27	Front / Logo / Replace	N
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
183	Wing Rear Right // Painting	N
211	Door Front Right // Smart Repair Medium	Y
320	Wheel Two Tone Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Door Front Right // Smart Repair Medium-scratch



Wing Rear Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Replace-cracked



Front / Logo / Replace-missing



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch