

INSPECTION REPORT


End of contract


GENERAL INFO

File	313328
License plate	JM6174
Vehicle identification number	VR3ECYHT2MJ598949
Dossier	2020 286 014
Make	Peugeot Rifter SWD HDi102 Acti
Mileage	145873
First registration	19/03/2021
client availability date	20/05/2026
inspectionDate	28/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
137	Bumper Rear // Replace without painting	N
155	Rear Bonnet // Replace & Painting	N
157	Rear Bonnet / Trim / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
66	Wing Front Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
226	Side View Mirror Right / Shell / Replace Painted	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
422	Seat Front Right / Bottom Coating / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Front Bonnet // Polish-Chemical reaction



Seat Front Right / Bottom Coating / Replace-tear



Interior Cleaning // Small-stain



Windshield // Repair-stone chipping



Rear Bonnet / Rear Window / Replace-scratch



Wing Front Left // Polish-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Side View Mirror Right / Shell / Replace Painted-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rear Bonnet // Replace & Painting-scratch + dent



Bumper Rear // Replace without painting-cracked



Rear Bonnet / Trim / Replace-cracked