

INSPECTION REPORT

End of contract

GENERAL INFO

File	307999
License plate	2CQT239
Vehicle identification number	VR3FCYHZLNY593821
Dossier	2022 213 022
Make	Peugeot 308 SW 1.5BHDi 130 All
Mileage	44372
First registration	21/10/2022
client availability date	13/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
274	Bumper Front / Grid Central / Replace	N
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
80	Door Front Left // Smart Repair Small	N
104	Door Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	N
225	Side View Mirror Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures





Damage within Renta-norm-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Smart Repair Small-dent



Door Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Tyre Front Right // Replace-tear