

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307514
License plate	1XLM927
Vehicle identification number	W1K1770841N151394
Dossier	2019 200 310
Make	Mercedes A 180 Bus.Solution Au
Mileage	115794
First registration	03/02/2020
client availability date	10/03/2026
inspectionDate	17/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	










Damage within Renta-norm-



Bumper Rear // Painting-scratch + dent



Tyre Front Left // Replace-worn




Tyre Front Right // Replace-worn



Door Front Right // Smart Repair Small-scratch





Side View Mirror Right // Polish-scratch



Wing Rear Left // Smart Repair Medium-scratch



Rear Bonnet // Polish-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent





Bumper Front // Painting-scratch



Side View Mirror Left // Polish-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Repair & Painting-scratch + dent