

INSPECTION REPORT

End of contract


GENERAL INFO

File	321180
License plate	AV4880
Vehicle identification number	W1K1770101J361633
Dossier	2022003014
Make	Mercedes A 180 d 116 Bus.Solut
Mileage	133845
First registration	22/07/2022
client availability date	31/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
891	Lettering Removal 15min	N
11	Bumper Front // Smart Repair Medium	N
78	Side View Mirror Left / Direction Indicator / Replace	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	N
135	Bumper Rear // Replace & Painting	N
150	Rear Bonnet // Smart Repair Small	N
190	Door Rear Right // Smart Repair Small	N
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	N
233	Wing Front right // Painting	N
569	Dashboard / Steering Wheel / Replace	Y


Damage Pictures



Light / Rear left / Replace-scratch



Bumper Front // Smart Repair Medium-scratch




Side View Mirror Left / Direction Indicator / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Right // Smart Repair Small-dent




Door Front Right // Smart Repair Small-dent



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Wing Front right // Painting-bad repair



Dashboard / Steering Wheel / Replace-worn



Bumper Rear // Replace & Painting-hole



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch



Lettering Removal 15min-