

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	281711
License plate	1XGU693
Vehicle identification number	WBA31AC0905P94119
Dossier	2019311206
Make	BMW X1 sDrive 16d 85kW
Mileage	129725.00
First registration	02/01/2020
	19/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES


Damages	Type	Acceptable
33	Front Bonnet // Repair & Painting	Y
74	Side View Mirror Left // Replace & Painting	Y
84	Door Front Left // Repair & Painting	Y
98	Rocker Panel Left / Cover Not Painted / Replace	N
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
151	Rear Bonnet // Smart Repair Medium	N
159	Rear Bonnet / Rear Window / Replace	N
174	Light / Rear Right / Replace	Y
214	Door Front Right // Repair & Painting	N
224	Side View Mirror Right // Replace & Painting	N
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures



Light / Rear Right / Replace-scratch






Rear Bonnet / Rear Window / Replace-scratch




Rear Bonnet // Smart Repair Medium-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Side View Mirror Right // Replace & Painting-scratch



Rocker Panel Left / Cover Not Painted / Replace-scratch




Door Rear Left // Polish-scratch




Wheel Alloy Front Left // Repair-scratch




Side View Mirror Left // Replace & Painting-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Bonnet // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Bumper Rear // Painting-bad repair