

INSPECTION REPORT




End of contract

GENERAL INFO

File	313604
License plate	SZ7649
Vehicle identification number	VSSZZKJZNR081915
Dossier	2021355020
Make	Seat Ibiza 1.0TSi 110 Style DS
Mileage	111506
First registration	30/03/2022
client availability date	22/05/2026
inspectionDate	27/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
81	Door Front Left // Smart Repair Medium	Y
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
222	Side View Mirror Right // Painting	Y
544	Interior / Floor Covering / Replace	N
549	Interior / Headliner/ Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
883	Key Price Range 2 //	N


Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Polish-scratch





Bumper Rear // Polish-scratch



Door Front Left // Smart Repair Medium-scratch




Bumper Front // Painting-scratch



Side View Mirror Right // Painting-scratch



Interior / Headliner/ Replace-Incinerated



Interior / Floor Covering / Replace-Incinerated