

INSPECTION REPORT

End of contract

GENERAL INFO

File	321106
License plate	2CHH946
Vehicle identification number	TMAJB812DNJ087427
Dossier	2021 278 084
Make	Hyundai Tuc.TGDi PHEV 195kW 4x
Mileage	86095
First registration	28/07/2022
client availability date	02/09/2026
inspectionDate	11/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
125	Light / Rear Left On Rear Bonnet / Replace	N
156	Rear Bonnet // Polish	N
116	Wing Rear Left // Polish	Y
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
330	Wheel Two Tone Rear Right // Repair	Y
413	Seat Front Left / Rear Coating / Replace	Y
421	Seat Front Right // Repair	Y

Damage Pictures




Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Polish-scratch




Door Front Right // Smart Repair Small-scratch



Seat Front Right // Repair-scratch



Seat Front Left / Rear Coating / Replace-worn



Wing Rear Left // Polish-scratch



Rear Bonnet // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch