

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	310041
License plate	2DFA805
Vehicle identification number	VF3VFEHS7PZ014101
Dossier	2022209192
Make	Peugeot Expert 2.0BHDi 145 Sta
Mileage	115880
First registration	28/02/2023
client availability date	07/04/2026
inspectionDate	15/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
149	Back Side / Park Assist Sensor / Replace	N
80	Door Front Left // Smart Repair Small	Y
87	Door Front Left / Trim / Replace	Y
89	Door Front Left / Window / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
113	Wing Rear Left // Painting	N
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	Y
422	Seat Front Right / Bottom Coating / Replace	N

## Damage Pictures



Door Rear Right // Repair & Painting-rust



Door Front Left / Window / Replace-scratch




Light / Rear Right / Replace-scratch



Wing Rear Left // Painting-scratch + dent



Door Front Left / Trim / Replace-scratch




Seat Front Right / Bottom Coating / Replace-scratch



Rocker Panel Left // Smart Repair Medium-dent




Door Front Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Rear Loading Door Left // Repair & Painting-scratch + dent




Rear Loading Door Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Repair & Painting-scratch + dent




Bumper Front // Painting-scratch






Bumper Front / Lower Cover Not Painted / Replace-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Back Side / Park Assist Sensor / Replace-cracked