

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	308718
License plate	2BFF464
Vehicle identification number	KMHC851CGNU266837
Dossier	2021 161 091
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	187401
First registration	29/10/2021
client availability date	20/03/2026
inspectionDate	25/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES


Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
54	Headlight / Front left / Replace	Y
63	Wing Front Left // Painting	N
86	Door Front Left // Polish	Y
87	Door Front Left / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
113	Wing Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
217	Door Front Right / Trim / Replace	N
236	Wing Front right // Polish	Y
244	Light / Front Right / Replace	Y
272	Bumper Front / Trim Right / Replace	N
282	Bumper Rear / Trim Center / Replace	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures





Wheel Alloy Rear Left // Repair-scratch




Wing Rear Left // Painting-scratch



Door Front Left // Polish-scratch



Wing Front Left // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch



Light / Front Right / Replace-scratch



Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Seat Front Left // Repair-scratch



Rocker Panel Left // Smart Repair Medium-scratch




Rear Left Door Interior Coating // Repair-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Bumper Rear / Trim Center / Replace-scratch + dent




Bumper Rear // Repair & Painting-scratch + dent




Door Front Left / Trim / Replace-Chemical reaction




Door Front Right / Trim / Replace-Chemical reaction



Interior // Repair 1-tear




Interior Cleaning // Small-stain



Front Bonnet // Painting-stone chipping



Wing Rear Right // Painting-scratch





Rear Bonnet // Polish-scratch



Light / Rear Right / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch