

INSPECTION REPORT

End of contract

GENERAL INFO

File	306437
License plate	2BSY923
Vehicle identification number	YV1XZL4V1N2762293
Dossier	2021 091 082
Make	Volvo XC40 T2 Momentum Pro
Mileage	121169
First registration	11/03/2022
client availability date	17/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
153	Rear Bonnet // Painting	Y
193	Door Rear Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
641	Rear Right Door Interior Coating // Repair	Y

Damage Pictures





Damage within Renta-norm-



Bumper Front // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Door Rear Right // Painting-scratch





Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Rear Bonnet // Painting-scratch



Bumper Rear // Repair & Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Rear Left // Painting-scratch