

INSPECTION REPORT



End of contract

GENERAL INFO

File	319760
License plate	2CAH686
Vehicle identification number	W1K1186841N304429
Dossier	2021 173 087
Make	Mercedes CLA SB 180 Bus.Soluti
Mileage	74051
First registration	10/05/2022
client availability date	14/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	Y
44	Windshield / Trim / Replace	N
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
136	Bumper Rear // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	N
421	Seat Front Right // Repair	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Interior // Repair 1-Incinerated



Windshield / Trim / Replace-tear




Tyre Rear Right // Replace-tear



Interior Cleaning // Small-stain



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rocker Panel Right // Smart Repair Medium-dent



Door Front Left // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Left // Polish-scratch





Wing Rear Left // Repair & Painting-scratch + dent