

INSPECTION REPORT


End of contract

GENERAL INFO

File	304213
License plate	1XQJ242
Vehicle identification number	W1K1770031N152559
Dossier	2019312229
Make	Mercedes A 180 d Bus Sol.
Mileage	51107
First registration	06/03/2020
client availability date	31/03/2026
inspectionDate	01/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	N
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	N
214	Door Front Right // Repair & Painting	Y
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N


Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch




Bumper Rear // Painting-scratch



Door Rear Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Rear Left // Repair & Painting-dent




Door Front Right // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Door Front Left // Smart Repair Medium-scratch + dent



Windshield // Repair-glass damage



Front Bonnet // Painting-stone chipping