

INSPECTION REPORT


End of contract

GENERAL INFO

File	309913
License plate	2ADM973
Vehicle identification number	VSSZZZKNZMW011369
Dossier	2020185081
Make	Seat Tarraco TSI 110kW Move
Mileage	80324
First registration	01/03/2021
client availability date	24/04/2026
inspectionDate	04/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES


Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
199	Door Rear Right / Window / Replace	Y
216	Door Front Right // Polish	Y
411	Seat Front Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	N
538	Trunk Compartment / Boot Cover / Replace	Y
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
840	Interior Cleaning // Large	N

Damage Pictures





Damage within Renta-norm-



Door Rear Right / Window / Replace-scratch




Door Front Right // Polish-scratch



Rear Right Door Interior Coating // Repair-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Seat Front Left // Repair-scratch




Trunk Compartment / Boot Cover / Replace-dent



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Large-dirty



Front Bonnet / Insulation / Replace-hole