

INSPECTION REPORT

End of contract


GENERAL INFO

File	312398
License plate	2CJH403
Vehicle identification number	VR3FRHNPLNY579139
Dossier	2021 363 256
Make	Peugeot 308 SW 1.2 110 Active
Mileage	109973
First registration	10/08/2022
client availability date	07/05/2026
inspectionDate	27/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
32	Front Bonnet // Painting	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
153	Rear Bonnet // Painting	N
161	Roof // Smart Repair Medium	N
174	Light / Rear Right / Replace	Y
193	Door Rear Right // Painting	Y
222	Side View Mirror Right // Painting	Y
234	Wing Front right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	Y
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
840	Interior Cleaning // Large	N
883	Key Price Range 2 //	N

Damage Pictures



Rear Bonnet // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Light / Rear Right / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wing Rear Left // Polish-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Front Bonnet // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Rear Right // Painting-scratch



Roof // Smart Repair Medium-dent



Wheel Rear Right / Wheel Cover / Replace-dent



Wing Front right // Repair & Painting-scratch + dent



Interior Cleaning // Large-stain