

INSPECTION REPORT


End of contract

GENERAL INFO

File	319633
License plate	2BHM906
Vehicle identification number	TMBJR9NU1N5021993
Dossier	2021 056 198
Make	Skoda Karoq 1.5TSI 110kW Cleve
Mileage	81751
First registration	29/11/2021
client availability date	27/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	N
124	Light / Rear left / Replace	N
134	Bumper Rear // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	Y
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	Y
84	Door Front Left // Repair & Painting	Y
103	Door Rear Left // Painting	Y
107	Door Rear Left / Trim / Replace	Y
139	Bumper Rear / Spoiler / Replace	N
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
162	Roof // Painting	N
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
234	Wing Front right // Repair & Painting	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures




Rocker Panel Right // Smart Repair Medium-scratch + dent





Rear Bonnet // Repair & Painting-scratch + dent



Bumper Rear / Spoiler / Replace-scratch + dent



Roof // Painting-bad repair




Interior Cleaning // Small-dirty



Front Bonnet / Insulation / Replace-bad position



Wheel Alloy Rear Left // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Alloy Rear Right // Repair-scratch




Rear Bonnet / Rear Window / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Door Rear Left // Painting-scratch




Rear Right Door Interior Coating // Replace Completely-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Windshield // Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Dashboard / Steering Wheel / Replace-scratch



Door Front Left // Repair & Painting-dent



Wing Front right // Repair & Painting-scratch + dent



Wing Rear Left // Painting-scratch



Light / Rear left / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent