

INSPECTION REPORT


End of contract

GENERAL INFO

File	321573
License plate	1WKY103
Vehicle identification number	VF3CUHMRPKY069768
Dossier	2019 049 137
Make	Peugeot 2008 1.2 61kW Active
Mileage	62156
First registration	28/06/2019
client availability date	04/09/2026
inspectionDate	17/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
81	Door Front Left // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
233	Wing Front right // Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Door Front Left // Smart Repair Medium-scratch



Wing Front right // Painting-scratch



Door Rear Right // Smart Repair Medium-scratch



Front Bonnet / Insulation / Replace-cracked



Windshield // Repair-cracked

