

INSPECTION REPORT

End of contract

GENERAL INFO

File	322589
License plate	2AJR038
Vehicle identification number	W1K2132121A970631
Dossier	2021 014 009
Make	Mercedes E Break 200 d 118kW B
Mileage	99772
First registration	16/04/2021
client availability date	18/09/2026
inspectionDate	24/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
234	Wing Front right // Repair & Painting	N
35	Front Bonnet // Polish	Y
83	Door Front Left // Painting	Y
131	Bumper Rear // Smart Repair Medium	Y
183	Wing Rear Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y

Damage Pictures



Front Bonnet // Polish-Chemical reaction



Wing Rear Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front right // Repair & Painting-scratch + dent



Bumper Front // Replace & Painting-cracked